

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

Denver & Rio Grande Rockwork
Approximately 21 - .6 of a Mile upstream from Keystone Bridge
in Watertown Vicinity
Jefferson(Douglas) Counties
Colorado

HAER CO-14

Documentation: 7 photographs (circa 1978)
1 data page

Photographers: Photos supplied by Denver Water Department

- C0-1 Rockwork approximately 6 of a mile upstream from Keystone Bridge. View looking south from a distance of 50 feet.
- C0-2 Rockwork on north bank of S. Platte River located 2.1 miles upstream from the Keystone Bridge. View looking northwest at a distance of 30 feet.
- C0-3 Rockwork on the north bank of the S. Platt River. Located approximately 2.3 miles upstream from Keystone Bridge.
- C0-4 Rockwork on north bank of the S. Platte River. Located approximately 2.4 miles upstream from Keystone Bridge and about 30 feet above river. View looking northwest from 70 feet.
- C0-5 Rockwork on the north bank of S. Platte River located approximately 5 of a mile downstream from Deansbury Bridge. View looking northwest from a distance of 50 feet.
- C0-6 Rockwork on north bank of S. Platte River. View looking northeast from a distance of 50 feet.
- C0-7 Rockwork on north bank of S. Platte River located approximately .3 of a mile downstream from the Deansbury Bridge. View looking northwest from a distance of 30 feet.